



Report Template Version: 1.1

03/31/2016 08:28:22 **Created On:**

District 1 Center:

Filter Parameters Selected: [From Event ID]: 294749, [From Date Time]: 02/21/2016 04:00, [To Date Time]: 02/21/2016 14:00,

[Road]: I-75, [Direction]: Southbound, [Event Status]: Any Valid

Period: 02/21/2016

Event(s) Found:

Event ID Range: 294,749

Event # : 294749	Event Type:	Crash		Report Date:	02/21/2016 04:58:33
Status:	Closed	County:	Sarasota	Organization:	SWIFT SunGuide
Last Status Time:	02/21/2016 19:21:22	Road:	I-75 SB	Notifier	FHP Troop F
Duration (mnt):	863	Location:	Exit 179 - TOLEDO BLADE BLVD	Agency:	1111 110001
First Notified:	02/21/2016 05:13:23			Notifier	FHP, FHP
Confirmed:	02/21/2016 05:04:23			Contact:	
First Closed:	02/21/2016 19:21:22	Rollover:	True	Conditions:	Wet, Clear, Dark (No Street Light)
Secondary to:		Fire:	False	CCTV ID:	689
FHP Incident Number:	FMRC16CAD020176	HAZMAT:	True	CCTV Preset:	2

Injury: Major, requiring treatment

Contacts:

Involved Vehicles		
Date	Туре	Description
02/21/2016 04:58:33	TMC NOTIFIED	FHP Troop F
02/21/2016 04:58:33	FHP	Alert received
02/21/2016 04:58:33	EVENT TYPE	Crash
02/21/2016 04:58:33	OWNER	shoots
02/21/2016 04:58:33	STATUS	Unconfirmed
02/21/2016 04:58:42	ATIS SEVERITY	minor
02/21/2016 04:58:42	LOCATION	Sarasota on I-75 Southbound, Before MILE MARKER 181
02/21/2016 04:58:43	FHP	New Event created based on FHP alert
02/21/2016 04:58:43	COMMENT	(Data) FHP Incident reported:
		FHP ID: FMRC16CAD020176
		County: sarasota
		Status: Update
		Source: FMRCC
		FHP Event Type: accidentsAndIncidents
		Location: I-75 South
		Author: MLT1336-CAD
		Remarks: roadblock
		Urgency: 10
		Desc: serious accident
		Start time: 02-21-2016 04:56:42
		Update time: 02-21-2016 04:57:57
		Trooper Dispatch time: 02-21-2016 04:57:50
02/21/2016 05:04:23	STATUS	Active
02/21/2016 05:04:32	LOCATION	Sarasota on I-75 Southbound, At MILE MARKER 178
02/21/2016 05:04:37	BLOCKAGE	Right Shoulder Blocked
02/21/2016 05:04:44	BLOCKAGE	Closed.

District 1 Created On: 03/31/2016 08:28:22 Page 1 of 17





		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 05:04:52	ATIS SEVERITY	major
02/21/2016 05:08:19	FHP	Update to FHP Alert received
02/21/2016 05:12:20	HAR	1934S 75 N/O JACARANDA M193: CRASH ON I-75
		SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (17)
02/21/2016 05:12:20	RESPONSE PLAN	Activated by user: shoots
02/21/2016 05:12:20	HAR	1612S 75 Tuckers Grade M161: CRASH ON I-75 SOUTHBOUND
		AT KINGS HIGHWAY. ALL LANES CLOSED. (18)
02/21/2016 05:12:20	HAR	1703N 75 Kings Hwy M170: CRASH ON I-75 SOUTHBOUND AT
02/21/2010 001/21/20		KINGS HIGHWAY. ALL LANES CLOSED. (9)
02/21/2016 05:12:20	HAR	1795N_75_N/O_Toledo_Blade_M179: CRASH_ON_I-75
02/21/2010 00:12:20		SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (3)
02/21/2016 05:12:20	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[NL]AT
02/21/2010 00:12:20	BING	KINGS HIGHWAY[NL]6 MI AHEAD (8)
02/21/2016 05:12:20	HAR	1644S 75 Duncan Road M164: CRASH ON I-75 SOUTHBOUND AT
02/21/2010 00:12:20	11/41	KINGS HIGHWAY. ALL LANES CLOSED. (14)
02/21/2016 05:12:20	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[NL]AT
02/21/2010 03.12.20	DIVIS	KINGS HIGHWAY[NL]3 MI AHEAD (5)
02/21/2016 05:12:20	HAR	1578S_75_Tuckers_Grade_M157: CRASH_ON_I-75 SOUTHBOUND
02/21/2010 05.12.20	HAR	AT KINGS HIGHWAY. ALL LANES CLOSED. (21)
02/21/2016 05:12:20	HAR	1671N_75_Harborview_M167: CRASH_ON_I-75 SOUTHBOUND AT
02/21/2010 03.12.20	ПАК	KINGS HIGHWAY. ALL LANES CLOSED. (12)
02/21/2016 05:12:20	LIAD	
02/21/2010 05.12.20	HAR	1824N_75_S/0_SUMTER_BLVD_M182: CRASH ON I-75
00/04/0046 05:40:04	FMANI	SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (6)
02/21/2016 05:12:21	EMAIL	Active Level 3:Crash::Sarasota I-75 SB At MILE MARKER
00/04/0040 05:40:04	DMC	178:Closed.::FDOT Central Office,Level 3 Sarasota Co.
02/21/2016 05:12:21	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER
00/04/0040 05 40 04	D110	178[nl]45 MI AHEAD (47)
02/21/2016 05:12:21	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE
	5.10	MARKER 178[ni]15 MI AHEAD (17)
02/21/2016 05:12:21	DMS	1980S_75_N/O_LAUREL_RD_M198: [jl3]I-75 CLOSED[nl]AT MILE
	5.15.10.1	MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 05:12:21	PUBLISH	Crash in Sarasota county, going Southbound on I-75 at MILE MARKER
		178 with All lanes blocked Last updated 2/21/2016 5:12:21 AM
02/21/2016 05:12:21	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[nl]AT MILE
		MARKER 178[nl]17 MI AHEAD (19)
02/21/2016 05:12:21	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE
		MARKER 178[nl]38 MI AHEAD (40)
02/21/2016 05:12:21	DMS	2194S_75_S/O_SR_64_M219: [jl3]I-75 CLOSED[nl]AT MILE MARKER
		178[nl]41 MI AHEAD (43)
02/21/2016 05:12:21	DMS	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE
		MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 05:12:21	HAR	2002N_75_N/O_SR_681_M200: CRASH ON I-75 SOUTHBOUND AT
		KINGS HIGHWAY. ALL LANES CLOSED. (21)
02/21/2016 05:12:21	DMS	2018S_75_N/O_SR_681_M202: [jl3]I-75 CLOSED[nl]AT MILE
		MARKER 178[nl]24 MI AHEAD (26)
02/21/2016 05:12:21	DMS	2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nl]AT MILE
		MARKER 178[nl]29 MI AHEAD (31)
02/21/2016 05:12:21	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE
		MARKER 178[nl]34 MI AHEAD (36)
02/21/2016 05:12:21	DMS	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nI]AT MILE
		MARKER 178[nl]49 MI AHEAD (51)





Report Template Version: 1.1

		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 05:12:22	DMS POSTED	1841S_75_N/O_PONCE_DELEON_M184: [jl3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]6 MI AHEAD
02/21/2016 05:12:23	DMS POSTED	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD
02/21/2016 05:12:23	DMS POSTED	1953S_75_N/O_BORDER_RD_M195: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]17 MI AHEAD
02/21/2016 05:12:24	DMS POSTED	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD
02/21/2016 05:12:24	DMS POSTED	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]24 MI AHEAD
02/21/2016 05:12:25	DMS POSTED	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD
02/21/2016 05:12:25	DMS POSTED	2066S_75_N/O_PROCTOR_RD_M207: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD
02/21/2016 05:12:26	DMS POSTED	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]34 MI AHEAD
02/21/2016 05:12:26	DMS POSTED	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD
02/21/2016 05:12:27	DMS POSTED	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]38 MI AHEAD
02/21/2016 05:12:27	DMS POSTED	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]45 MI AHEAD
02/21/2016 05:12:28	DMS POSTED	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD
02/21/2016 05:12:28	DMS POSTED	2194S_75_S/O_SR_64_M219: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]41 MI AHEAD
02/21/2016 05:12:30	TMC NOTIFIED	RTMC Verified Correct
02/21/2016 05:12:32	CONTACT	RTMC Verified Correct: HAR Beacons:
02/21/2016 05:12:35	CONTACT	RTMC Verified Correct: HAR Message:
02/21/2016 05:12:38	CONTACT	RTMC Verified Correct: DMS Signs:
02/21/2016 05:12:40	CONTACT	RTMC Verified Correct: 511 System:
02/21/2016 05:12:58	TMC NOTIFIED	Traffic Management Centers
02/21/2016 05:13:03	CONTACT	Traffic Management Centers: TMC 1: Scott
02/21/2016 05:13:23	TMC NOTIFIED	FDOT
02/21/2016 05:13:25	CONTACT	FDOT: Robbie Brown:
02/21/2016 05:16:01	TMC NOTIFIED	RISC - Prompt Towing
02/21/2016 05:17:06	CONTACT	RISC - Prompt Towing: Initial Call to Tow Agency : Jeff
02/21/2016 05:17:13	TMC NOTIFIED	FHP Troop F
02/21/2016 05:17:21	CONTACT	FHP Troop F: FHP Dispatch: Daniel
02/21/2016 05:18:21	COMMENT	(RTMC Operator:) Per FHP DO Maeder: DBI enroute
02/21/2016 05:19:32	COMMENT	(RTMC Operator:) Per FHP DO Maeder: 1 Tanker 500 gallons of fuel, emptied on I75 at mm 178 SB, full closer, one entrapment and injuries





Report Template Version: 1.1

Date	Туре	Description
02/21/2016 05:20:08	COMMENT	(Data) FHP Incident reported:
		FHP ID: FMRC16CAD020176
		County: sarasota
		Status: Update
		Source: FMRCC
		FHP Event Type: accidentsAndIncidents
		Location: I-75 South
		Author: MLT1336-CAD
		Remarks: roadblock southbound
		Urgency: 10
		Desc: serious accident
		Start time: 2/21/2016 4:56:42 AM
		Update time: 2/21/2016 5:07:58 AM
		Trooper Dispatch time: 2/21/2016 4:57:50 AM
02/21/2016 05:20:08	FHP	FHP Alert Associated to event
02/21/2016 05:23:13	FHP	Update to FHP Alert received
02/21/2016 05:24:00	COMMENT	(RTMC Operator:) Per TMC: Jeff (Prompt Towing) 941-639-4000,
		notified at 05:15am
02/21/2016 05:25:45	COMMENT	(Data) FHP Incident reported:
		FHP ID: FMRC16CAD020176
		County: sarasota
		Status: Update
		Source: FMRCC
		FHP Event Type: accidentsAndIncidents
		Location: I-75 South
		Author: MLT1336-CAD
		Remarks: roadblock southbound
		Urgency: 10
		Desc: injury accident
		Start time: 2/21/2016 4:56:42 AM
		Update time: 2/21/2016 5:22:58 AM
		Trooper Dispatch time: 2/21/2016 4:57:50 AM
02/21/2016 05:25:45	FHP	FHP Alert Associated to event
02/21/2016 05:26:08	FIRST ARRIVED	FHP Troop F
02/21/2016 05:26:27	CONTACT	Emergency Responders: Fire Department:
02/21/2016 05:26:30	CONTACT	Emergency Responders: E M S:
02/21/2016 05:26:31	FIRST ARRIVED	Emergency Responders
02/21/2016 05:26:38	CONTACT	County and Local Law Enforcement: County Sheriff:
02/21/2016 05:26:39	FIRST ARRIVED	County and Local Law Enforcement
02/21/2016 05:28:21	FHP	Update to FHP Alert received
02/21/2016 05:29:37	FHP	FHP Alert Associated to event





Date	
FHP ID: FMRC16CAD020176 County: sarasota Status: Update Source: FMRCC FHP Event Type: accidents Andincidents Location: I-75 South Author: MLT1336-CAD Remarks: roadblock southbound Urgency: 10 Desc: injury accident Statt time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:28:04 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM Trooper Dispatch time: 2/21/2016 5:28:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM Trooper Dispatch time: 2/21/2016 5:28:36 AM Trooper Dispatch time: 2/21/2016 5:28:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM Trooper Dispatch time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 A	
County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: roadblock southbound Urgency: 10 Desc: injury accident Start time: 2/21/2016 5:28:36 AM Trooper Olspatch time: 2/21/2016 5:28:36 AM Trooper Arrival time: 2/21/2016	
Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: roadblock southbound Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:28:04 AM Trooper Dispatch time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:28:04 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM Trooper Dispatch time: 2/21/2016 5:38:37 FHP Update to FHP Alert received Traffic Management Centers: TMC 7: Mike Traffic Management Centers: TMC 7: Mike Dispatch time: 2/21/2016 05:38:37 FHP Update to FHP Alert received Update Traffic Management Centers: TMC 7: Mike Dispatch time: 2/21/2016 05:38:37 FHP Update to FHP Alert received Update Update	
Source: FMRCC	
FHP Event Type: accidentsAndIncidents	
Location: I-75 South	
Author: MLT1336-CAD Remarks: roadblock southbound Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 5:25:36 AM Trooper Dispatch time: 2/21/2016 5:35:04 TMC NOTIFIED Traffic Management Centers: TMC 7: Mike 02/21/2016 05:38:37 FHP Update to FHP Alert received 02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported: FHP ID: FMRC16CAD020176 County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:33:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Arrival time: 2/21/2016 4:57:50 AM 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct RTMC Verified Correct FTMC Verified Correct	
Remarks: roadblock southbound Urgency: 10	
Urgency: 10	
Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:35:04 TMC NOTIFIED Traffic Management Centers: TMC 7: Mike 02/21/2016 05:38:37 FHP Update to FHP Alert received 02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported: FHP ID: FMRC16CAD020176 County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Arrival time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FH Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct: Floodgate Message: ENG	
Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:28:04 AM Update time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:35:02 CONTACT Traffic Management Centers: TMC 7: Mike O2/21/2016 05:35:04 TMC NOTIFIED Traffic Management Centers TmC 7: Mike O2/21/2016 05:38:37 FHP Update to FHP Alert received Update to FHP Alert received O2/21/2016 05:39:19 COMMENT (Data) FHP Incident reported: FHP ID: FMRC16CAD020176 County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Arrival time: 2/21/2016 4:57:50 AM Trooper Start time: 2/21/2016 4:57:50 AM Trooper Arrival time: 2/21/2016 4:57:50 AM Trooper Start time: 2/21/2016 6:457:50 AM Trooper Arrival time: 2/21/2016 6:457:50 AM Troope	
Update time: 2/21/2016 5:28:04 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 6:23:36 AM Trooper Dispatch time: 2/21/2016 6:23:36 AM Trooper Dispatch time: 2/21/2016 6:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:35:04 TMC NOTIFIED Traffic Management Centers 02/21/2016 05:38:37 FHP Update to FHP Alert received 02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported: FHP ID: FMRC16CAD020176 County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:35:02 CONTACT Traffic Management Centers: TMC 7: Mike 02/21/2016 05:35:04 TMC NOTIFIED Traffic Management Centers: TMC 7: Mike 02/21/2016 05:38:37 FHP Update to FHP Alert received 02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported: FHP ID: FMRC16CAD020176 County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct FHM Palert Associated Message: ENG	
Trooper Dispatch time: 2/21/2016 4:57:50 AM	
02/21/2016 05:35:02 CONTACT Traffic Management Centers: TMC 7: Mike 02/21/2016 05:35:04 TMC NOTIFIED Traffic Management Centers 02/21/2016 05:38:37 FHP Update to FHP Alert received 02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported:	
02/21/2016 05:35:04 TMC NOTIFIED Traffic Management Centers 02/21/2016 05:38:37 FHP Update to FHP Alert received 02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported:	
02/21/2016 05:35:04 TMC NOTIFIED Traffic Management Centers 02/21/2016 05:38:37 FHP Update to FHP Alert received 02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported:	
02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported:	
02/21/2016 05:39:19 COMMENT (Data) FHP Incident reported:	
FHP ID: FMRC16CAD020176 County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
County: sarasota Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Status: Update Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Source: FMRCC FHP Event Type: accidentsAndIncidents Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Location: I-75 South Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Author: MLT1336-CAD Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Remarks: complete road block south bound i-75 - seek alternate route Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Urgency: 10 Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Desc: injury accident Start time: 2/21/2016 4:56:42 AM Update time: 2/21/2016 5:35:37 AM Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Start time: 2/21/2016 4:56:42 AM	
Update time: 2/21/2016 5:35:37 AM	
Trooper Arrival time: 2/21/2016 5:23:36 AM Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
Trooper Dispatch time: 2/21/2016 4:57:50 AM 02/21/2016 05:39:19 FHP FHP Alert Associated to event 02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
02/21/2016 05:39:19FHPFHP Alert Associated to event02/21/2016 05:41:32TMC NOTIFIEDRTMC Verified Correct02/21/2016 05:42:40CONTACTRTMC Verified Correct: Floodgate Message: ENG	
02/21/2016 05:41:32 TMC NOTIFIED RTMC Verified Correct 02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
02/21/2016 05:42:40 CONTACT RTMC Verified Correct: Floodgate Message: ENG	
· · ·	
172010 00.42.40 CONTROL	
02/21/2016 05:42:51 TMC NOTIFIED Traffic Management Centers	
02/21/2016 05:47:49 COMMENT (RTMC Operator:) Per TMC Sup. C McVeigh, notified Tampa TMC for	
more signs	
02/21/2016 05:49:40 COMMENT (RTMC Operator:) Per CCTV 1778S at preset 36 can also view front	
visual of tanker across all lanes and into the median	
02/21/2016 05:49:53 FIRST ARRIVED Emergency Responders 02/21/2016 05:50:27 COMMENT (PTMC Operators) Per CCTV: Towy truck is an econo @ 05:40	
02/21/2016 05:50:27 COMMENT (RTMC Operator:) Per CCTV: Tow truck is on scene @ 05:49	
02/21/2016 05:52:26 COMMENT (RTMC Operator:) Per FHP: notified fuel is diesel	
02/21/2016 05:55:10 COMMENT (RTMC Operator:) Per FHP DO Maeder: DBI eta is 45 minutes	
02/21/2016 05:58:33 COMMENT (RTMC Operator:) Per DBI Braden: enroute eta 15 mins	
02/21/2016 06:01:35 COMMENT (RTMC Operator:) Per FHP DO Maeder: tanker is now 1500 gallons of	
diesel, emptied	
02/21/2016 06:05:04 TMC NOTIFIED Maintenance & Traffic Engineering	
02/21/2016 06:05:44 CONTACT Maintenance & Traffic Engineering: D O C: Kevin/ voicemail	





OF THIS		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 06:07:48	DMS POSTED	2227S_N/O_KAY_RD_M223: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]44 MI AHEAD.
02/21/2016 06:07:48	DMS POSTED	2066S_75_N/O_PROCTOR_RD_M207: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]28 MI AHEAD.
02/21/2016 06:07:48	DMS POSTED	1841S_75_N/O_PONCE_DELEON_M184: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]5 MI AHEAD.
02/21/2016 06:07:48	DMS POSTED	1980S_75_N/O_LAUREL_RD_M198: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]19 MI AHEAD.
02/21/2016 06:07:48	DMS POSTED	2277S_75_S/O_69TH_ST_M228: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]48 MI AHEAD.
02/21/2016 06:07:48	DMS POSTED	2157S_75_S/O_LINGER_LODGE_M216: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]37 MI AHEAD.
02/21/2016 06:07:48	DMS POSTED	1809S_75_S/O_SUMTER_BLVD_M181: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]2 MI AHEAD.
02/21/2016 06:07:49	DMS POSTED	2018S_75_N/O_SR_681_M202: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]23 MI AHEAD.
02/21/2016 06:07:49	DMS POSTED	2123S_75_N/O_SR_780_M212: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]33 MI AHEAD.
02/21/2016 06:07:49	DMS POSTED	1931S_75_S/O_JACARANDA_M193: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]14 MI AHEAD.
02/21/2016 06:07:49	DMS POSTED	1953S_75_N/O_BORDER_RD_M195: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]16 MI AHEAD.
02/21/2016 06:07:49	DMS POSTED	2090S_75_S/O_PALMER_BLVD_M209: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]30 MI AHEAD.
02/21/2016 06:07:49	DMS POSTED	2194S_75_S/O_SR_64_M219: Message Replaced by user rmikol with message [pt30o0][jl3]I-75 CLOSED[NL]BEYOND TOLEDO BLADE[NL]40 MI AHEAD.
02/21/2016 06:09:45	COMMENT	(RTMC Operator:) Per Joe Prompt Towing is on scene, with all equipment
02/21/2016 06:09:47	FIRST ARRIVED	RISC - Prompt Towing
02/21/2016 06:09:52	CONTACT	RISC - Prompt Towing: On Scene Time :
02/21/2016 06:10:44	COMMENT	(RTMC Operator:) Per FHP DO Maeder: motorist has been retrieved and transported to hospital with broken leg.
02/21/2016 06:11:33	COMMENT	(RTMC Operator:) Per FHP DO Maeder: waiting on hazmat for fuel
02/21/2016 06:13:03	OWNER	rmikol
02/21/2016 06:13:28	COMMENT	(RTMC Operator:) TMC advised District 7 to update their signs
02/21/2016 06:21:28	CONTACT	Asset Management-DBI: DBI Maintenance: Richard Fimble
02/21/2016 06:22:29	COMMENT	(RTMC Operator:) Richard Fimble advised the TMC that his arrival time will be 30 minutes or less.





most likely be an all day event.	OF TRA		Report Template Version: 1.1
as close to the scene as emergency (responders will allow them.) (RTMC Operator) per FHP dispatch, all responders will the exception of fire is staged at least 300 feet behind scene. (RTMC Operator) per FHP dispatch, there is 8500 gallons of diesel on the ground, per google semi trankers carry around 9000 gallons. TMC is unaware of total of remaining diesel in tanker 20/21/2016 06:39:25 CONTACT FDOT: Emergency Operations Centrers: Kevins Salisbury of all detals and severity of this incident. TMC advised FDOT District 1 EOC Kevins Salisbury of all detals and severity of this incident. TMC advised EOC that this wind and severity of this incident. TMC advised EOC that this winder the pound, per google semi tranker carry around 9000 gallons. TMC is unaware of total of remaining diesel in tanker 20/21/2016 06:40:39 COMMENT (RTMC Operator) TMC advised FDOT District 1 EOC Kevins Salisbury of all detals and severity of this incident. TMC advised EOC that this winder the process of the process of the process of the process of seminary and severe the process of the process of 20/21/2016 06:41:56 CONTACT Traffic Management Centers: TMC 2: David (RTMC Operator) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator) TMC advised PMC TMC TMC TMC TMC TMC TMC TMC TMC TMC T	Date	Туре	Description
Of fire is staged at least 300 feet behind scene.	02/21/2016 06:28:47	COMMENT	
the ground, per google semi tankers carry around 900 gallons. TMC is unaware of total of remaining diesel in tanker 02/21/2016 06:39:25 CONTACT FDOT: Emergency Operations Centers: Kevin Salisbury (RTMC Operator); TMC advised FDOT District 1 EOC Kevin Salisbury of all details and severity of this incident. TMC advised EOC that this wimost likely be an all day event. 17affic Management Centers 17affic Management Centers 17affic Management Centers: TMC 2: David 02/21/2016 06:41:47 TMC NOTIFIED Traffic Management Centers: TMC 2: David 02/21/2016 06:42:51 COMMENT (RTMC Operator.) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. 02/21/2016 06:44:49 COMMENT (RTMC Operator.) Per CCTV. Fire is in the process of spraying the fluir on the road. 02/21/2016 07:08:03 CONTACT Asset Management-DBI: DBI Maintenance: Richard Fimble Update to FHP Alert received 02/21/2016 07:08:03 CONTACT (RTMC Operator.) Per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warning point has been contacted and cleanup crew is on the way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator.) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:22:32 RESPONSE PLAN Activated by user: milkol 02/21/2016 07:22:32 PAR 16:43	02/21/2016 06:30:56	COMMENT	
Unaware of total of remaining diesel in tanker 02/21/2016 06:40:39 CONTACT FDOT: Emergency Operations Centers: Kevin Salisbury 02/21/2016 06:40:39 COMMENT (RTMC Operator.) TMC advised FDOT District 1 EOC Kevin Salisbury of all details and severity of this incident. TMC advised EOC that this wi most likely be an all day event. TMC NOTIFIED Traffic Management Centers 02/21/2016 06:41:47 TMC NOTIFIED Traffic Management Centers: TMC 2: David 02/21/2016 06:42:51 COMMENT (RTMC Operator.) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. 02/21/2016 06:42:51 COMMENT (RTMC Operator.) Per CCTV , Fire is in the process of spraying the fluid on the road. 02/21/2016 06:46:25 FIRST ARRIVED Asset Management-DBI 02/21/2016 07:08:03 CONTACT Asset Management-DBI: DBI Maintenance: Richard Fimble 02/21/2016 07:08:40 FHP Update to FHP Alert received 02/21/2016 07:12:06 COMMENT (RTMC Operator.) Per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warring point has been contacted and cleanup crew is on the way Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator.) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:22:32 HAR 16:43 F. Duncan Road M164: CRASH ON 1-75 SOUTHBOUND A' KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 DMS 26:68_75_BVIO_PROCTOR_RD_M181: [ji]3]-75 CLOSED[nl]AT MILE MARKER 178[ni]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 18:98_75_BVIO_RROCTOR_RD_M181: [ji]3]-75 CLOSED[nl]AT MILE MARKER 178[ni]194 MI AHEAD (28) 02/21/2016 07:22:32 DMS 19:91_75 CLOSED[nl]AT MILE MARKER 178[ni]194 MI AHEAD (28) 02/21/2016 07:22:32 DMS 20:91_91_91_AT MILE MARKER 178[ni]194 MI AHEAD (28)	02/21/2016 06:37:41	COMMENT	
OZ/21/2016 06:40:39 COMMENT (RTMC Operator.) TMC advised FDOT District 1 EOC Kevin Salisbury of all details and severity of this incident. TMC advised EOC that this wi most likely be an all day event.		2217127	unaware of total of remaining diesel in tanker
of all details and severity of this incident. TMC advised EOC that this wimost likely be an all day event. Traffic Management Centers OZ/21/2016 06.41:56 CONTACT Traffic Management Centers: TMC 2: David OZ/21/2016 06.42:51 COMMENT OZ/21/2016 06.42:51 COMMENT OZ/21/2016 06.44:49 COMMENT (RTMC Operator.) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator.) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator.) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator.) TMC advised David With District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. (RTMC Operator.) TMC advised Fire in the process of spraying the fluid on the road. OZ/21/2016 07:08:03 COMTACT Asset Management-DBI: DBI Maintenance: Richard Fimble OZ/21/2016 07:08:04 FHP Update to FHP Alert received (RTMC Operator.) per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warning point has been contacted and cleanup crew is on the way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. (RTMC Operator.) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:22:32 HAR 1644S, 75 Duncan Road, M164: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. [14] 02/21/2016 07:22:32 DMS 1895 75 N/O PROCTOR RD M207: [19]1-75 CLOSED[n]AT MILE MARKER 178[n]28 MI AHEAD (3) 02/21/2016 07:22:32 DMS 1931S, 75 SIO_SHARED READ (17) 1902/21/2016 07:22:32 DMS 1931S, 75 SIO_SHARED READ (17) 1903 1931S, 75 CLOSED[n]AT MILE MARKER 178[n]31 MI AHEAD (28) 1903 1931S, 75 SIO_PALMER BLVD_M200; [13]1-75 CLOSED[n]AT MILE MARKER 178[n]31 MI AHEAD (3)			
02/21/2016 06:41:47 TMC NOTIFIED Traffic Management Centers 02/21/2016 06:44:56 CONTACT Traffic Management Centers: TMC 2: David 02/21/2016 06:42:51 COMMENT (RTIMC Operator:) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. 02/21/2016 06:44:49 COMMENT (RTIMC Operator:) Per CCTV , Fire is in the process of spraying the fluid on the road. 02/21/2016 07:08:03 CONTACT Asset Management-DBI: DBI Maintenance: Richard Fimble 02/21/2016 07:08:04 FHP Update to FHP Alert received 02/21/2016 07:12:06 COMMENT (RTIMC Operator:) per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warning point has been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTIMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:16:57 SECONDARY 294750 02/21/2016 07:22:32 HAR 1644S_75 Duncan_Road_M164: CRASH ON I-75 SOUTHBOUND A' KINGS HIGHWAY, ALL LANES CLOSED. (14) 02/21/2016	02/21/2016 06:40:39	COMMENT	of all details and severity of this incident. TMC advised EOC that this will
02/21/2016 06:41:56 CONTACT Traffic Management Centers: TMC 2: David 02/21/2016 06:42:51 COMMENT (RTMC Operator:) TMC advised David with District 2 TMC that Spanish Floodgate needed to be changed to reflect current conditions. 02/21/2016 06:44:49 COMMENT (RTMC Operator:) Per CCTV , Fire is in the process of spraying the fluid on the road. 02/21/2016 07:08:03 FIRST ARRIVED Asset Management-DBI DBI Maintenance: Richard Fimble 02/21/2016 07:08:46 FHP Update to FHP Pether received 02/21/2016 07:12:06 COMMENT (RTMC Operator:) per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warning point has been contacted and cleanup crew is not he way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:16:43 ESCONDARY 294750 02/21/2016 07:22:32 RESPONSE PLAN Activated by user: rmikol 02/21/2016 07:22:32 HAR 16448, 75 Duncan_Road_M164: CRASH ON 1-75 SOUTHBOU	02/21/2016 06:41:47	TMC NOTIFIED	
COMMENT			
Floodgate needed to be changed to reflect current conditions.			
O2/21/2016 06:44:49 COMMENT CRTMC Operator:) Per CCTV , Fire is in the process of spraying the flui on the road. Oxide to ad. Oxide			
02/21/2016 07:08:03 CONTACT Asset Management-DBI: DBI Maintenance: Richard Fimble 02/21/2016 07:08:46 FHP Update to FHP Alert received 02/21/2016 07:12:06 COMMENT (RTMC Operator:) per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warning point has been contacted and cleanup crew is on the way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:16:57 SECONDARY 294750 02/21/2016 07:22:31 RESPONSE PLAN Activated by user: rmikol 02/21/2016 07:22:32 HAR 1644S, 75 Duncan Road_M164: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N_75_Harborview_M167: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[n]29 MI AHEAD (3) 02/21/2016 07:22:32 DMS 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT	02/21/2016 06:44:49	COMMENT	(RTMC Operator:) Per CCTV , Fire is in the process of spraying the fluid on the road.
02/21/2016 07:08:46 FHP Update to FHP Alert received 02/21/2016 07:12:06 COMMENT (RTMC Operator:) per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warning point has been contacted and cleanup crew is on the way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:22:31 RESPONSE PLAN Activated by user: rmikol 02/21/2016 07:22:32 HAR 1644S_75_Duncan_Road_M164: CRASH_ON_L75_SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N_75_Harborview_M167: CRASH_ON_L75_SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[ni]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nL]AT KINGS HIGHWAY. ALL LANES CLOSED. (2) 02/21/2016 07:22:32 HAR 1578S_75_Tuckers_Grade_M157: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 <td>02/21/2016 06:46:25</td> <td>FIRST ARRIVED</td> <td>Asset Management-DBI</td>	02/21/2016 06:46:25	FIRST ARRIVED	Asset Management-DBI
02/21/2016 07:12:06 COMMENT (RTMC Operator:) per Richard Fimble, Prompt Towing has 2 heavy tow trucks on scene plus two rollbacks. State warning point has been contacted and cleanup crew is on the way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:22:31 RESPONSE PLAN Activated by user: rmikol 02/21/2016 07:22:32 HAR 1644S_75_Duncan_Road_M164: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N_75_Harborview_M167: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (9) 02/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1578S_75_NO_ACRANDA_M193: [ji3]I-75 CLOSED[nI]	02/21/2016 07:08:03	CONTACT	Asset Management-DBI: DBI Maintenance: Richard Fimble
trucks on scene plus two rollbacks. State warning point has been contacted and cleanup crew is on the way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 2/21/2016 07:16:57 SECONDARY 294750 2/21/2016 07:22:31 RESPONSE PLAN Activated by user: rmikol 2/21/2016 07:22:32 HAR 1648_75_Duncan_Road_M164: CRASH ON I-75 SOUTHBOUND A' KINGS HIGHWAY. ALL LANES CLOSED. (14) 2/21/2016 07:22:32 DMS 1671N_75_Harborview_M167: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 2/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD (31) 2/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY[NL]3 MI AHEAD (5) 2/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (9) 2/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (9) 2/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (21) 2/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (21) 2/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (21) 2/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY, ALL LANES CLOSED. (21) 2/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 2/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 2/21/2016 07:22:32 DMS 1578S_70_PALMER BLVD_M209: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]24 MI AHEAD (26) 2/2016 07:22:32 DMS 1578	02/21/2016 07:08:46	FHP	Update to FHP Alert received
Contacted and cleanup crew is on the way. Richard also stated that Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. O2/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. O2/21/2016 07:22:31 RESPONSE PLAN Activated by user: milkol	02/21/2016 07:12:06	COMMENT	
Construction companies have been contacted because road will have to be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:22:31 RESPONSE PLAN Activated by user: mikol 02/21/2016 07:22:32 HAR 1644S, 75_Duncan_Road_M164: CRASH ON I-75 SOUTHBOUND A' KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N, 75_Harborview_M167: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S, 75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]29 MI AHEAD (31) 02/21/2016 07:22:32 HAR 1793N, 75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1703N, 75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2098_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2099S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26)			
be repaved. Richard also stated that He can be contact person on scene for the remainder of the incident. 02/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:16:57 SECONDARY 294750 02/21/2016 07:22:31 RESPONSE PLAN Activated by user: rmikol 02/21/2016 07:22:32 HAR 1644S, 75_Duncan_Road_M164: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N, 75_Harborview_M167: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S, 75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD (5) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (26)			·
Scene for the remainder of the incident.			
02/21/2016 07:16:43 COMMENT (RTMC Operator:) TMC advised RR Supervisor Bob Diezi so that Road Ranger covered beats could be adjusted. 02/21/2016 07:22:31 SECONDARY 294750 02/21/2016 07:22:32 RESPONSE PLAN Activated by user: rmikol 02/21/2016 07:22:32 HAR 1644S_75_Duncan_Road_M164: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N_75_Harborview_M167: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nL]AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1578S_75_Tuckers_Grade_M157: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1578S_75_JUCKERS_Grade_M157: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2058_75_S/O_PALMER_BLVD_M209: [ji3]I-75			·
Ranger covered beats could be adjusted.	00/04/0040 07:40:40	COMMENT	
02/21/2016 07:22:31 RESPONSE PLAN Activated by user: rmikol 02/21/2016 07:22:32 HAR 1644S_75_Duncan_Road_M164: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N_75_Harborview_M167: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD (5) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1578S_75_Tuckers_Grade_M157: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS			Ranger covered beats could be adjusted.
02/21/2016 07:22:32 HAR 1644S_75_Duncan_Road_M164: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N_75_Harborview_M167: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[n]]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD (5) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (33)			
KINGS HIGHWAY. ALL LANES CLOSED. (14) 02/21/2016 07:22:32 HAR 1671N_75_Harborview_M167: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[n]]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD (5) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[n]]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[n]]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[n]]31 MI AHEAD (33)			
KINGS HIGHWAY. ALL LANES CLOSED. (12) 02/21/2016 07:22:32 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD (5) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 DMS 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (33)	02/21/2016 07:22:32	HAR	KINGS HIGHWAY. ALL LANES CLOSED. (14)
MARKER 178[ni]29 MI AHEAD (31) 02/21/2016 07:22:32 DMS	02/21/2016 07:22:32	HAR	KINGS HIGHWAY. ALL LANES CLOSED. (12)
02/21/2016 07:22:32 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [jl3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD (5) 02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)	02/21/2016 07:22:32	DMS	
02/21/2016 07:22:32 HAR 1703N_75_Kings_Hwy_M170: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9) 02/21/2016 07:22:32 HAR 1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (33)	02/21/2016 07:22:32	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [jl3]I-75 CLOSED[NL]AT
KINGS HIGHWAY. ALL LANES CLOSED. (9) 1578S_75_Tuckers_Grade_M157: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17) 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33)			
AT KINGS HIGHWAY. ALL LANES CLOSED. (21) 02/21/2016 07:22:32 DMS	02/21/2016 07:22:32	HAR	
02/21/2016 07:22:32 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17) 02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33) MARKER 178[ni]31 MI AHEAD (33)	02/21/2016 07:22:32	HAR	
02/21/2016 07:22:32 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26) 02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (33)	02/21/2016 07:22:32	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE
02/21/2016 07:22:32 DMS 2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)	02/21/2016 07:22:32	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE
	02/21/2016 07:22:32	DMS	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nl]AT MILE
KINGS HIGHWAY[NL]6 MI AHEAD (8)	02/21/2016 07:22:32	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[NL]AT
02/21/2016 07:22:32 HAR 1824N_75_S/0_SUMTER_BLVD_M182: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (6)	02/21/2016 07:22:32	HAR	1824N_75_S/0_SUMTER_BLVD_M182: CRASH ON I-75





Date 02/21/2016 07:22:32 02/21/2016 07:22:32 02/21/2016 07:22:32 02/21/2016 07:22:32	Type HAR DMS DMS DMS	Description 1795N_75_N/O_Toledo_Blade_M179: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (3) 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40) 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]45 MI AHEAD (47)
02/21/2016 07:22:32 02/21/2016 07:22:32	DMS DMS	SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (3) 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40) 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]45 MI AHEAD (47)
02/21/2016 07:22:32	DMS	MARKER 178[ni]38 MI AHEAD (40) 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]45 MI AHEAD (47)
		178[nl]45 MI AHEAD (47)
02/21/2016 07:22:32	DMS	00770 75 0/0 00711 07 M000 EVEN 75 00 00771 11 11 11 11
		2277S_75_S/O_69TH_ST_M228: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 07:22:32	HAR	1934S_75_N/O_JACARANDA_M193: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (17)
02/21/2016 07:22:32	HAR	2002N_75_N/O_SR_681_M200: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21)
02/21/2016 07:22:32	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19)
02/21/2016 07:22:32	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]20 MI AHEAD (22)
02/21/2016 07:22:32	DMS	2123S_75_N/O_SR_780_M212: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]34 MI AHEAD (36)
02/21/2016 07:22:32	DMS	2194S_75_S/O_SR_64_M219: [jl3]Í-75 CLOSED[nl]AT MILE MARKER 178[nl]41 MI AHEAD (43)
02/21/2016 07:22:32	HAR	1612S_75_Tuckers_Grade_M161: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (18)
02/21/2016 07:22:33	PUBLISH	Crash in Sarasota county, going Southbound on I-75 at MILE MARKER 178 with All lanes blocked Last updated 2/21/2016 7:22:32 AM
02/21/2016 07:32:54	CONTACT	Asset Management-DBI: DBI Maintenance: Richard Fimble
02/21/2016 07:35:16	COMMENT	(RTMC Operator:) per Richard Fimble with DBI. HAZMAT cleanup crew have arrived on scene. SWS Hazmat has been contacted and is sending 2 units to assist in cleanup. Per Richard FHP is driving the proposed detour route before route is activated.
02/21/2016 07:36:09	COMMENT	(RTMC Operator:) per CCTV , additional fire equipment has arrived and is staging to the South of the scene.
02/21/2016 07:42:35	COMMENT	(RTMC Operator:) Per CCTV , there is 12 Fire and Hazmat units currently on scene.
02/21/2016 07:43:24	COMMENT	(RTMC Operator:) Per Richard with DBI, Construction companies have been notified and plans for repaving are in the works.
02/21/2016 07:54:25	CONTACT	FDOT: (PIO): Robin Steuben
02/21/2016 07:55:03	COMMENT	(RTMC Operator:) TMC advised FDOT PIO Robin Steublin of Current situation
02/21/2016 07:57:54	COMMENT	(RTMC Operator:) TMC left message with FDOT ITS Manager advising of severity of this incident.
02/21/2016 08:00:32	COMMENT	(RTMC Operator:) per CCTV s additional Fire trucks and a fire response vehicle have approached from the South and are staged just south of rolled over tanker.
02/21/2016 08:07:24	COMMENT	(RTMC Operator:) per CCTV Foam is being sprayed on tanker by multiple fire response vehicles.
02/21/2016 08:30:37	COMMENT	(RTMC Operator:) all RISC activities are suspended while HAZMAT situation is taken care of.
02/21/2016 08:39:46	RESPONSE PLAN	Activated by user: rmikol
02/21/2016 08:39:47	HAR	1934S_75_N/O_JACARANDA_M193: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (17)
02/21/2016 08:39:47	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]17 MI AHEAD (19)





OF TRA		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 08:39:47	DMS	2018S_75_N/O_SR_681_M202: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]24 MI AHEAD (26)
02/21/2016 08:39:47	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36)
02/21/2016 08:39:47	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]45 MI AHEAD (47)
02/21/2016 08:39:47	HAR	1703N_75_Kings_Hwy_M170: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (9)
02/21/2016 08:39:47	HAR	1824N_75_S/0_SUMTER_BLVD_M182: CRÁSH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (6)
02/21/2016 08:39:47	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17)
02/21/2016 08:39:47	DMS	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33)
02/21/2016 08:39:47	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]38 MI AHEAD (40)
02/21/2016 08:39:47	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [jl3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]3 MI AHEAD (5)
02/21/2016 08:39:47	HAR	1644S_75_Duncan_Road_M164: CRASH_ON_I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (14)
02/21/2016 08:39:47	HAR	1671N_75_Harborview_M167: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (12)
02/21/2016 08:39:47	DMS	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 08:39:47	HAR	1578S_75_Tuckers_Grade_M157: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21)
02/21/2016 08:39:47	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLÓSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 08:39:47	DMS	2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]29 MI AHEAD (31)
02/21/2016 08:39:47	DMS	2194S_75_S/O_SR_64_M219: [j 3]I-75 CLOSED[n]AT MILE MARKER 178[n]41 MI AHEAD (43)
02/21/2016 08:39:47	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[NL]AT KINGS HIGHWAY[NL]6 MI AHEAD (8)
02/21/2016 08:39:47	HAR	1612S_75_Tuckers_Grade_M161: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (18)
02/21/2016 08:39:47	HAR	1795N_75_N/O_Toledo_Blade_M179: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (3)
02/21/2016 08:39:47	HAR	2002N_75_N/O_SR_681_M200: CRASH ON I-75 SOUTHBOUND AT KINGS HIGHWAY. ALL LANES CLOSED. (21)
02/21/2016 08:39:48	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 at MILE MARKER 178 with All lanes blocked Last updated 2/21/2016 8:39:47 AM
02/21/2016 09:53:06	HAR	1612S_75_Tuckers_Grade_M161(51:har:har:District 1): Blank
02/21/2016 09:53:06	HAR	1934S_75_N/O_JACARANDA_M193(62:har:har:District 1): Blank
02/21/2016 09:53:06	RESPONSE PLAN	Activated by user: rmikol
02/21/2016 09:53:06	HAR	1703N_75_Kings_Hwy_M170(54:har:har:District 1): Blank
02/21/2016 09:53:06	HAR	1671N_75_Harborview_M167(53:har:har:District 1): Blank
02/21/2016 09:53:06	HAR	1578S_75_Tuckers_Grade_M157(86:har:har:District 1): Blank
02/21/2016 09:53:06	HAR	1644S_75_Duncan_Road_M164(52:har:har:District 1): Blank
02/21/2016 09:53:07	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]45 MI AHEAD (47)





OF TRI		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 09:53:07	DMS	1841S_75_N/O_PONCE_DELEON_M184: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]6 MI AHEAD (8)
02/21/2016 09:53:07	HAR	1795N_75_N/O_Toledo_Blade_M179(56:har:har:District 1): Blank
02/21/2016 09:53:07	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36)
02/21/2016 09:53:07	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]3 MI AHEAD (5)
02/21/2016 09:53:07	HAR	1824N_75_S/0_SUMTER_BLVD_M182(87:har:har:District 1): Blank
02/21/2016 09:53:07	DMS	1953S_75_N/O_BORDER_RD_M195: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]17 MI AHEAD (19)
02/21/2016 09:53:07	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]24 MI AHEAD (26)
02/21/2016 09:53:07	DMS	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]49 MI AHEAD (51)
02/21/2016 09:53:07	HAR	2002N_75_N/O_SR_681_M200(64:har:har:District 1): Blank
02/21/2016 09:53:07	DMS	2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 09:53:07	DMS	1931S_75_S/O_JACARANDA_M193: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]15 MI AHEAD (17)
02/21/2016 09:53:07	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 09:53:07	DMS	2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD (31)
02/21/2016 09:53:07	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40)
02/21/2016 09:53:07	DMS	2194S_75_S/O_SR_64_M219: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]41 MI AHEAD (43)
02/21/2016 09:53:08	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 at MILE MARKER 178 with All lanes blocked Last updated 2/21/2016 9:53:07 AM
02/21/2016 10:21:50	CONTACT	Traffic Management Centers: TMC 7:
02/21/2016 10:24:40	CONTACT	Maintenance & Traffic Engineering: County Traffic Engineering: Charlotte- Rich
02/21/2016 10:26:52	COMMENT	(RTMC Operator:) TMC was advised by Rich Lisenbee with Charlotte County Traffic Engineering that all signal timing on US 41 that he controls have been adjusted. Mr Lisenbee has also advised that he will drive to scene to attempt to adjust signal timing in construction areas as well
02/21/2016 10:27:38	COMMENT	(RTMC Operator:) Charlotte County has reported that delays caused by this incident are not severe at this time.
02/21/2016 10:30:04	COMMENT	(RTMC Operator:) TMC updated TMC 7 with estimation that roadway will be shut down for the remainder of the day.
02/21/2016 10:38:30	CONTACT	Asset Management-DBI: DBI Maintenance: Richard Fimble
02/21/2016 10:57:52	COMMENT	(RTMC Operator:) TMC was updated by DBI Richard Fimble that detour signs and personnel are almost in place.
02/21/2016 10:59:27	COMMENT	(RTMC Operator:) per CCTV, responders on scene total 60 plus vehicles for this incident.
02/21/2016 11:04:39	COMMENT	(RTMC Operator:) per CCTV , there are at least 3 vehicles on scene from SWS environmental services.
02/21/2016 11:30:50	COMMENT	(RTMC Operator:) per FHP dispatch RISC was initially called at 05:07 by Sergeant Roberts from FHP.
02/21/2016 11:43:54	COMMENT	(RTMC Operator:) per CCTV , tail of congestion is mm 180.6 SB





OF THI		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 11:52:41	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19)
02/21/2016 11:52:41	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40)
02/21/2016 11:52:41	DMS	2066S_75_N/O_PROCTOR_RD_M207: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD (31)
02/21/2016 11:52:41	DMS	2194S_75_S/O_SR_64_M219: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]41 MI AHEAD (43)
02/21/2016 11:52:41	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]3 MI AHEAD (5)
02/21/2016 11:52:41	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]6 MI AHEAD (8)
02/21/2016 11:52:41	RESPONSE PLAN	Activated by user: rmikol
02/21/2016 11:52:41	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nl]AT MILE
02/21/2010 11.32.41	DIVIO	MARKER 178[nl]24 MI AHEAD (26)
02/21/2016 11:52:41	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER
		178[nl]45 MI AHEAD (47)
02/21/2016 11:52:41	DMS	2277S_75_S/O_69TH_ST_M228: [jl3]I-75 CLOSED[nl]AT MILE
		MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 11:52:41	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE
		MARKER 178[nl]15 MI AHEAD (17)
02/21/2016 11:52:41	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nl]AT MILE
		MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 11:52:41	DMS	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 11:52:41	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]34 MI AHEAD (36)
02/21/2016 11:52:42	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 at MILE MARKER 178 with All lanes blocked Last updated 2/21/2016 11:52:41 AM
02/21/2016 12:41:05	COMMENT	(RTMC Operator:) TMC located debris on CCTV 1916NB
02/21/2016 12:50:46	COMMENT	(RTMC Operator:) per CCTV , SWS environmental services is on scene
		and working on cleanup. per CCTV , all technicians in direct vicinity of rolled over tanker are wearing full protective gear including oxygen tanks.
02/21/2016 13:31:49	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 13:31:49	DMS	2227S_N/O_KAY_RD_M223: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]45 MI AHEAD (47)
02/21/2016 13:31:49	RESPONSE PLAN	Activated by user: rmikol
02/21/2016 13:31:49	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]17 MI AHEAD (19)
02/21/2016 13:31:49	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]38 MI AHEAD (40)
02/21/2016 13:31:49	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]6 MI AHEAD (8)
02/21/2016 13:31:49	DMS	2066S_75_N/O_PROCTOR_RD_M207: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD (31)
02/21/2016 13:31:49	DMS	2018S_75_N/O_SR_681_M202: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]24 MI AHEAD (26)
02/21/2016 13:31:49	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36)
		. , ,





OF TRAIL		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 13:31:49	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17)
02/21/2016 13:31:49	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]3 MI AHEAD (5)
02/21/2016 13:31:49	DMS	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33)
02/21/2016 13:31:49	DMS	2194S_75_S/O_SR_64_M219: [j 3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]41 MI AHEAD (43)
02/21/2016 13:31:49	DMS	2277S_75_S/O_69TH_ST_M228: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 13:31:50	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 at MILE MARKER 178 with All lanes blocked Last updated 2/21/2016 1:31:49 PM
02/21/2016 14:03:08	OWNER	kgibbons
02/21/2016 14:03:51	COMMENT	(RTMC Operator:) as per CCTV all Emergency Vehicles still on scene
02/21/2016 14:06:45	RESPONSE PLAN	Activated by user: kgibbons
02/21/2016 14:06:45	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]15 MI AHEAD (17)
02/21/2016 14:06:45	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]17 MI AHEAD (19)
02/21/2016 14:06:46	DMS	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 14:06:46	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]38 MI AHEAD (40)
02/21/2016 14:06:46	DMS	2194S_75_S/O_SR_64_M219: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]41 MI AHEAD (43)
02/21/2016 14:06:46	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]45 MI AHEAD (47)
02/21/2016 14:06:46	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]6 MI AHEAD (8)
02/21/2016 14:06:46	DMS	2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]29 MI AHEAD (31)
02/21/2016 14:06:46	DMS	2277S_75_S/O_69TH_ST_M228: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 14:06:46	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36)
02/21/2016 14:06:46	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 14:06:46	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26)
02/21/2016 14:06:46	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]3 MI AHEAD (5)
02/21/2016 14:06:47	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 at MILE MARKER 178 with All lanes blocked Last updated 2/21/2016 2:06:46 PM
02/21/2016 14:07:08	CONTACT	RTMC Verified Correct: DMS Signs:
02/21/2016 14:07:11	CONTACT	RTMC Verified Correct: 511 System:
02/21/2016 14:07:15	CONTACT	RTMC Verified Correct: Floodgate Message:
02/21/2016 14:09:39	COMMENT	(RTMC Operator:) as per TMC still waiting on the RISC activation
02/21/2016 14:11:57	BLOCKAGE	No Lanes Blocked.
02/21/2016 14:11:57	LOCATION	Sarasota on I-75 Southbound, Beyond Exit 179 - TOLEDO BLADE BLVD





OF THIS		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 14:12:03	BLOCKAGE	Closed.
02/21/2016 14:13:06	OWNER	rmikol
02/21/2016 14:16:11	DMS	2194S_75_S/O_SR_64_M219: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]41 MI AHEAD (43)
02/21/2016 14:16:11	RESPONSE PLAN	Activated by user: rmikol
02/21/2016 14:16:11	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]45 MI AHEAD (47)
02/21/2016 14:16:11	DMS	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 14:16:11	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36)
02/21/2016 14:16:11	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40)
02/21/2016 14:16:12	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19)
02/21/2016 14:16:12	DMS	2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD (31)
02/21/2016 14:16:12	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]15 MI AHEAD (17)
02/21/2016 14:16:12	DMS	2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 14:16:12	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]3 MI AHEAD (5)
02/21/2016 14:16:12	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]20 MI AHEAD (22)
02/21/2016 14:16:12	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26)
02/21/2016 14:16:12	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]6 MI AHEAD (8)
02/21/2016 14:16:13	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 beyond Exit 179 - TOLEDO BLADE BLVD with All lanes blocked Last updated 2/21/2016 2:16:12 PM
02/21/2016 14:21:53	OWNER	kgibbons
02/21/2016 14:22:19	COMMENT	(RTMC Operator:) as per TMC still waiting on the RISC activation
02/21/2016 14:58:41	DMS	2123S_75_N/O_SR_780_M212: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]34 MI AHEAD (36)
02/21/2016 14:58:41	RESPONSE PLAN	Activated by user: kgibbons
02/21/2016 14:58:41	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40)
02/21/2016 14:58:41	DMS	2194S_75_S/O_SR_64_M219: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]41 MI AHEAD (43)
02/21/2016 14:58:42	DMS	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]49 MI AHEAD (51)
02/21/2016 14:58:42	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]3 MI AHEAD (5)
02/21/2016 14:58:42	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]15 MI AHEAD (17)
02/21/2016 14:58:42	DMS	2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 14:58:42	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22)





OFTRI		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 14:58:42	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]6 MI AHEAD (8)
02/21/2016 14:58:42	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26)
02/21/2016 14:58:42	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]17 MI AHEAD (19)
02/21/2016 14:58:42	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 beyond Exit 179 - TOLEDO BLADE BLVD with All lanes blocked Last updated 2/21/2016 2:58:42 PM
02/21/2016 14:58:42	DMS	2227S_N/O_KAY_RD_M223: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]45 MI AHEAD (47)
02/21/2016 14:58:42	DMS	2066S_75_N/O_PROCTOR_RD_M207: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD (31)
02/21/2016 14:58:58	CONTACT	RTMC Verified Correct: DMS Signs:
02/21/2016 14:59:01	CONTACT	RTMC Verified Correct: 511 System:
02/21/2016 15:48:06	COMMENT	(RTMC Operator:) as per CCTV Tow Truck is Moving Semi on to Truck for removal
02/21/2016 16:11:51	COMMENT	(RTMC Operator:) as per TMC contacted Prompt Towing Diane, advised to have someone on location to call and advise updates and need to know information.
02/21/2016 16:25:18	COMMENT	(RTMC Operator:) as per TMC contacted Edward @ Prompt Towing he advised they were given notice to proceed and I (quote) sometime before 4:00pm
02/21/2016 17:02:06	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]45 MI AHEAD (47)
02/21/2016 17:02:06	DMS	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 17:02:06	DMS	1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 17:02:06	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17)
02/21/2016 17:02:06	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]6 MI AHEAD (8)
02/21/2016 17:02:06	DMS	2018S_75_N/O_SR_681_M202: [ji3]i-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26)
02/21/2016 17:02:06	DMS	2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 17:02:06	RESPONSE PLAN	Activated by user: kgibbons
02/21/2016 17:02:06	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40)
02/21/2016 17:02:06	DMS	2194S_75_S/O_SR_64_M219: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]41 MI AHEAD (43)
02/21/2016 17:02:06	DMS	2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]29 MI AHEAD (31)
02/21/2016 17:02:06	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36)
02/21/2016 17:02:06	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]3 MI AHEAD (5)
02/21/2016 17:02:06	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19)





OF TRA		Report Template Version: 1.1
Date	Туре	Description
02/21/2016 17:02:08	PUBLISH	Crash involving hazardous materials in Sarasota county, going Southbound on I-75 beyond Exit 179 - TOLEDO BLADE BLVD with All lanes blocked Last updated 2/21/2016 5:02:06 PM
02/21/2016 17:02:41	CONTACT	RTMC Verified Correct: DMS Signs:
02/21/2016 17:02:44	CONTACT	RTMC Verified Correct: 511 System:
02/21/2016 17:02:48	CONTACT	RTMC Verified Correct: Floodgate Message:
02/21/2016 17:02:52	CONTACT	RTMC Verified Correct: HAR Beacons:
02/21/2016 17:02:58	CONTACT	RTMC Verified Correct: HAR Message:
02/21/2016 17:05:49	COMMENT	(RTMC Operator:) as per CCTV Tanker has been loaded on Tow Truck
02/21/2016 17:06:56	COMMENT	(RTMC Operator:) as per CCTV workers are throwing sand and oil dry on roadway
02/21/2016 17:18:53	COMMENT	(RTMC Operator:) as per Richard with DBI advised order to proceed was at 4:00 pm Tow Trucks have loaded Tractor and Tanker and will be leaving scene.
02/21/2016 17:20:31	COMMENT	(RTMC Operator:) as per Richard with DBI a Paving Crew is enroute
		they will start paving one lane at a time to try and get one lane open
02/21/2016 17:23:27	COMMENT	(RTMC Operator:) as per Richard with DBI emergency construction and
		hazmat will continue for the next two weeks to remove spilled fuel in
		bar-ditches on both sides of roadway
02/21/2016 17:25:08	COMMENT	(RTMC Operator:) Richard with DBI advised that southbound will be
		closed until around 10:00pm to 11:00pm until one lane gets paved
02/21/2016 17:33:57	COMMENT	(RTMC Operator:) as per FHP Stephaney: advised time to proceed was
		given at 15:00 hours 3:00pm
02/21/2016 17:34:05	CONTACT	Maintenance & Traffic Engineering: D O C:
02/21/2016 17:35:12	CONTACT	Maintenance & Traffic Engineering: D O C: Oscar
02/21/2016 17:35:32	CONTACT	Traffic Management Centers: TMC 7: Chad
02/21/2016 17:36:20	COMMENT	(RTMC Operator:) TMC advised DOC Oscar of road blocked till
		10:00pm
02/21/2016 17:37:10	COMMENT	(RTMC Operator:) TMC advised Dist. 7 DMS signs will be running till 10:00pm
02/21/2016 17:53:30	DMS	2277S_75_S/O_69TH_ST_M228: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]49 MI AHEAD (51)
02/21/2016 17:53:30	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19)
02/21/2016 17:53:30	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]34 MI AHEAD (36)
02/21/2016 17:53:30	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]3 MI AHEAD (5)
02/21/2016 17:53:30	DMS	1980S_75_N/O_LAUREL_RD_M198: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22)
02/21/2016 17:53:30	RESPONSE PLAN	Activated by user: kgibbons
02/21/2016 17:53:30	DMS	2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]45 MI AHEAD (47)
02/21/2016 17:53:30	DMS	2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33)
02/21/2016 17:53:30	DMS	1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]6 MI AHEAD (8)
02/21/2016 17:53:30	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17)
02/21/2016 17:53:30	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40)





Description	OF THIS		Report Template Version: 1.1
178[n] 4 MI A-IEAD (43)	Date	Туре	Description
O2/21/2016 17:53:30 DMS 2018S 75.N/O_SR_681_M202: [II3]I-75 CLOSED[nI]AT MILE	02/21/2016 17:53:30		
D2/21/2016 17:53:30 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[ni]29 MI AHEAD (31)	02/21/2016 17:53:30	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE
O2/21/2016 17:53:31 PUBLISH Crash involving hazardous materials in Sarasota county, going Southbound on I-75 beyond Exit 179 - TOLEDO BLADE BLVD with All lanes blocked Last updated 2/21/2016 5:33:30 PM	02/21/2016 17:53:30	DMS	2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE
lanes blocked Last updated 2/21/2016 5:53:30 PM	02/21/2016 17:53:31	PUBLISH	Crash involving hazardous materials in Sarasota county, going
02/21/2016 17:54:08 CONTACT RTMC Verified Correct: Floodgate Message: 02/21/2016 17:54:12 CONTACT RTMC Verified Correct: 511 System: 02/21/2016 17:54:14 CONTACT RTMC Verified Correct: 511 System: 02/21/2016 18:31:53 COMMENT (RTMC Operator:) as per CCTV Construction Crew on scene 02/21/2016 18:39:25 DMS 2194S_75_5/O_SR_64_M219: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]4 MI AHEAD (43) 02/21/2016 18:39:25 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]29 MI AHEAD (31) 02/21/2016 18:39:25 DMS 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]29 MI AHEAD (47) 02/21/2016 18:39:25 DMS 1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]34 MI AHEAD (47) 02/21/2016 18:39:25 DMS 1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (19) 02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (26) 02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33) 02/21/2016 18:39:25 DMS 209S_75_N/O_DALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (32) 02/21/2016 18:39		CONTACT	lanes blocked Last updated 2/21/2016 5:53:30 PM
O2/21/2016 17:54:12 CONTACT RTMC Verified Correct: DMS Signs: O2/21/2016 17:54:14 CONTACT RTMC Verified Correct: 511 System: O2/21/2016 18:31:53 COMMENT (RTMC Operator:) as per CCTV Construction Crew on scene O2/21/2016 18:39:25 DMS 21945_75_5/O_SR_64_M219: [ji3]I-75 CLOSED[ni]AT MILE MARKER O2/21/2016 18:39:25 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[ni]AT MILE MARKER O2/21/2016 18:39:25 DMS 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[ni]AT MILE MARKER O2/21/2016 18:39:25 DMS 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[ni]AT MILE MARKER O2/21/2016 18:39:25 DMS 1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[ni]AT MILE MARKER O2/21/2016 18:39:25 DMS 1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19) O2/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (26) O2/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33) O2/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33) O2/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]20 MI AHEAD (22) O2/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]30 MI AHEAD (26) O2/21/2016 18:39:25 DMS 2123S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]34 MI AHEAD (36) O2/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]34 MI AHEAD (36) O2/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]34 MI AHEAD (47) O2/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]34 MI AHEAD (47)			
02/21/2016 17:54:14 CONTACT RTMC Verified Correct: 511 System: 02/21/2016 18:31:53 COMMENT (RTMC Operator:) as per CCTV Construction Crew on scene 02/21/2016 18:39:25 DMS 2194S_75_S/O_SR_64_M219: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]41 MI AHEAD (43) 02/21/2016 18:39:25 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]29 MI AHEAD (31) 02/21/2016 18:39:25 DMS 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]45 MI AHEAD (47) 02/21/2016 18:39:25 DMS 1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]45 MI AHEAD (8) 02/21/2016 18:39:25 DMS 1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19) 02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26) 02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33) 02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]30 MI AHEAD (36) 02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOS			<u> </u>
O2/21/2016 18:31:53 COMMENT CRTMC Operator:) as per CCTV Construction Crew on scene			•
02/21/2016 18:39:25 DMS 2194S_75_S/O_SR_64_M219: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]14 MI AHEAD (43) 02/21/2016 18:39:25 DMS 2066S_75_N/O_PROCTOR_RD_M207: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]29 MI AHEAD (31) 02/21/2016 18:39:25 DMS 2227S_N/O_KAY_RD_M223: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]45 MI AHEAD (47) 02/21/2016 18:39:25 DMS 1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]6 MI AHEAD (8) 02/21/2016 18:39:25 DMS 1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]17 MI AHEAD (19) 02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]24 MI AHEAD (26) 02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (33) 02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]20 MI AHEAD (22) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36) 02/21/2016 18:39:25			
178[n] 41 MI AHEAD (43)			
MARKER 178[ni]29 MI AHEAD (31)	02/21/2016 18:39:25	DMS	178[nl]41 MI AHEAD (43)
178[ni]45 MI AHEAD (47) 02/21/2016 18:39:25 DMS 1841S_75_N/O_PONCE_DELEON_M184: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]6 MI AHEAD (8) 02/21/2016 18:39:25 DMS 1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19) 02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26) 02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33) 02/21/2016 18:39:25 RESPONSE PLAN Activated by user: kgibbons 02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]20 MI AHEAD (22) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]34 MI AHEAD (36) 02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17) 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (40)	02/21/2016 18:39:25	DMS	
MILE MARKER 178[ni]6 MI AHEAD (8) 02/21/2016 18:39:25 DMS 1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]17 MI AHEAD (19) 02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]24 MI AHEAD (26) 02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]31 MI AHEAD (33) 02/21/2016 18:39:25 DMS 2090S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]20 MI AHEAD (22) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]30 MI AHEAD (36) 02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]15 MI AHEAD (17) 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]38 MI AHEAD (40)	02/21/2016 18:39:25	DMS	~
02/21/2016 18:39:25 DMS 1953S_75_N/O_BORDER_RD_M195: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 RESPONSE PLAN Activated by user: kgibbons 02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 1931S_75_S/O_LINGER_LODGE_M216: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [jl3]I-75 CLOSED[nl]AT MILE 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [jl3]I-75 CLOSED[nl]AT MILE	02/21/2016 18:39:25	DMS	
02/21/2016 18:39:25 DMS 2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nI]AT MILE 02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]31 MI AHEAD (33) MARKER 178[nI]31 MI AHEAD (33) 02/21/2016 18:39:25 DMS Activated by user: kgibbons 02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]20 MI AHEAD (22) MARKER 178[nI]31 MI AHEAD (36) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36) 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40) MARKER 178[nI]38 MI AHEAD (40)	02/21/2016 18:39:25	DMS	1953S_75_N/O_BORDER_RD_M195: [ji3]I-75 CLOSED[nI]AT MILE
02/21/2016 18:39:25 DMS 2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]31 MI AHEAD (33) 02/21/2016 18:39:25 RESPONSE PLAN Activated by user: kgibbons 02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]20 MI AHEAD (22) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]34 MI AHEAD (36) 02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]15 MI AHEAD (17) 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [jl3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]38 MI AHEAD (40)	02/21/2016 18:39:25	DMS	2018S_75_N/O_SR_681_M202: [ji3]I-75 CLOSED[nl]AT MILE
02/21/2016 18:39:25 RESPONSE PLAN Activated by user: kgibbons 02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]20 MI AHEAD (22) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36) 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40) MARKER 178[nI]38 MI AHEAD (40)	02/21/2016 18:39:25	DMS	2090S_75_S/O_PALMER_BLVD_M209: [jl3]I-75 CLOSED[nl]AT MILE
02/21/2016 18:39:25 DMS 1980S_75_N/O_LAUREL_RD_M198: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]20 MI AHEAD (22) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36) 02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40)	02/21/2016 18:39:25	RESPONSE PLAN	
MARKER 178[ni]20 MI AHEAD (22) 02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[ni]34 MI AHEAD (36) 02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[ni]15 MI AHEAD (17) 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[ni]38 MI AHEAD (40)			
02/21/2016 18:39:25 DMS 2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]34 MI AHEAD (36) 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]15 MI AHEAD (17) 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE MARKER 178[nI]38 MI AHEAD (40) MARKER 178[nI]38 MI AHEAD (40)	02/21/2010 10:00:20	DINIO	
02/21/2016 18:39:25 DMS 1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]15 MI AHEAD (17) 02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]38 MI AHEAD (40)	02/21/2016 18:39:25	DMS	2123S_75_N/O_SR_780_M212: [ji3]I-75 CLOSED[nI]AT MILE
02/21/2016 18:39:25 DMS 2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nl]AT MILE MARKER 178[nl]38 MI AHEAD (40)	02/21/2016 18:39:25	DMS	1931S_75_S/O_JACARANDA_M193: [ji3]I-75 CLOSED[ni]AT MILE
	02/21/2016 18:39:25	DMS	2157S_75_S/O_LINGER_LODGE_M216: [ji3]I-75 CLOSED[nI]AT MILE
MARKER 178[nl]49 MI AHEAD (51)	02/21/2016 18:39:25	DMS	2277S_75_S/O_69TH_ST_M228: [ji3]I-75 CLOSED[nI]AT MILE
02/21/2016 18:39:25 DMS 1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[ni]AT MILE MARKER 178[ni]3 MI AHEAD (5)	02/21/2016 18:39:25	DMS	1809S_75_S/O_SUMTER_BLVD_M181: [ji3]I-75 CLOSED[nl]AT MILE
02/21/2016 18:39:26 PUBLISH Crash involving hazardous materials in Sarasota county, going	02/21/2016 18:39:26	PUBLISH	Crash involving hazardous materials in Sarasota county, going
Southbound on I-75 beyond Exit 179 - TOLEDO BLADE BLVD with All lanes blocked Last updated 2/21/2016 6:39:25 PM			lanes blocked Last updated 2/21/2016 6:39:25 PM
02/21/2016 18:39:54 CONTACT RTMC Verified Correct: DMS Signs:			•
02/21/2016 18:40:00 CONTACT RTMC Verified Correct: :			
02/21/2016 19:11:51 SECONDARY 294864		SECONDARY	
02/21/2016 19:14:44 LAST DEPARTED FHP Troop F			•
02/21/2016 19:14:50 CONTACT County and Local Law Enforcement: :	02/21/2016 19:14:50	CONTACT	County and Local Law Enforcement: :
02/21/2016 19:14:51 LAST DEPARTED County and Local Law Enforcement	02/21/2016 19:14:51	LAST DEPARTED	County and Local Law Enforcement
02/21/2016 19:15:16 FHP FHP Alert Associated to event	02/21/2016 19:15:16	FHP	FHP Alert Associated to event





Report Template Version: 1.1

Date	Туре	Description
02/21/2016 19:17:42	COMMENT	(RTMC Operator:) as per CCTV due to Paving Crew on scene and
		emergency Vehicles have Departed TMC will close event to make room
		for emergency construction event #294864
02/21/2016 19:18:15	BLOCKAGE	No Lanes Blocked.
02/21/2016 19:18:20	LAST DEPARTED	Asset Management-DBI
02/21/2016 19:18:22	ATIS SEVERITY	minor
02/21/2016 19:18:29	CONTACT	Emergency Responders: Tow Truck:
02/21/2016 19:18:30	LAST DEPARTED	Emergency Responders
02/21/2016 19:19:30	DMS	2123S_75_N/O_SR_780_M212(349:dms:dms:District 1): Blank
02/21/2016 19:19:30	DMS	2157S_75_S/O_LINGER_LODGE_M216(351:dms:dms:District 1):
		Blank
02/21/2016 19:19:30	RESPONSE PLAN	Activated by user: kgibbons
02/21/2016 19:19:31	DMS	2194S_75_S/O_SR_64_M219(352:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	1931S_75_S/O_JACARANDA_M193(339:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	1953S_75_N/O_BORDER_RD_M195(341:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	1841S_75_N/O_PONCE_DELEON_M184(336:dms:dms:District 1):
		Blank
02/21/2016 19:19:31	DMS	2090S 75 S/O PALMER BLVD M209(347:dms:dms:District 1): Blank
02/21/2016 19:19:31	EMAIL	Cleared:Crash: Rollover:Sarasota I-75 SB Beyond Exit 179 TOLEDO
		BLADE BLVD:No Lanes Blocked.:HAZMAT :FDOT Central Office,Level
		3 Sarasota Co.
02/21/2016 19:19:31	DMS	2018S 75 N/O SR 681 M202(343:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	2277S 75 S/O 69TH ST M228(357:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	1809S_75_S/O_SUMTER_BLVD_M181(358:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	2066S 75 N/O PROCTOR RD M207(345:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	2227S N/O KAY RD M223(355:dms:dms:District 1): Blank
02/21/2016 19:19:31	DMS	1980S_75_N/O_LAUREL_RD_M198(342:dms:dms:District 1): Blank
02/21/2016 19:19:32	PUBLISH	Crash involving hazardous materials in Sarasota county, going
		Southbound on I-75 beyond Exit 179 - TOLEDO BLADE BLVD Last
		updated 2/21/2016 7:19:31 PM
02/21/2016 19:19:36	UNPUBLISH	Removed event from FL-ATIS 511 system.
02/21/2016 19:19:36	RESPONSE PLAN	Terminated by user: kgibbons
02/21/2016 19:20:22	RESPONSE PLAN	Terminated by user: kgibbons
02/21/2016 19:20:23	UNPUBLISH	Removed event from FL-ATIS 511 system.
02/21/2016 19:20:39	CONTACT	RTMC Verified Clear: DMS Signs :
02/21/2016 19:20:42	CONTACT	RTMC Verified Clear: 511? System :
02/21/2016 19:20:46	CONTACT	RTMC Verified Clear: HAR Message :
02/21/2016 19:20:49	CONTACT	RTMC Verified Clear: HAR Beacons :
02/21/2016 19:20:52	CONTACT	RTMC Verified Clear: Floodgate Message :
02/21/2016 19:21:22	STATUS	Closed
02/21/2016 19:21:23	UNPUBLISH	Removed event from FL-ATIS 511 system.
02/21/2016 20:33:35	EVENT ASSOCIATION	Event has been unassociated with Secondary Event (294750)
02/21/2016 20:33:48	EVENT ASSOCIATION	Event has been unassociated with Secondary Event (294864)
02,21,2010 20.00.40	2.211.70000///1014	275.11 Had book andooodated with occording Event (207007)